



- NOTES
1. SEE ARCH. & MECH. FOR SHUT MITL CAP & OTHER ITEMS NOT SHOWN.
 2. SEE (1) & (3) FOR PLATFORM & ROOF PENETRATIONS.
 3. ALL ISOLATORS SHALL BE ANCHORED THRU PLUMB INTO TO THE 2 OF A 4x8 MEMBER AS SHOWN. USING 2.5x4x4 LAG BOLTS & FA ISOLATOR. INSTALL BOLTS IN PRE-DRILLED HOLES AS PER SPECIFICATIONS ON SHUT S-1.



NO.	REVISION	DATE	BY

FIRE MARSHAL

IDENTIFICATION STAMP
Department of General Services
Office of the State Architect

APR 4 1991
Structural Safety Section
No. A 55660
Issued by J.P./L.A.

O.S.A.

Glenn Hartzell A.I.A.
26 'H' STREET, 93304 (805) 324-6416
P.O. BOX 2344, 93303, BAKERSFIELD, CALIFORNIA
ARCHITECT C-10298

REGISTERED PROFESSIONAL ARCHITECT
STATE OF CALIFORNIA
No. 2528
Exp. 3-31-99

DATE: 1-11-91
DRAWN: J.O.F.
CHECKED: J.O.F.

DETAILS (AIR CONDITIONING)
HORT SCHOOL
BAKERSFIELD CITY SCHOOL DISTRICT
2301 PARK DRIVE, BAKERSFIELD, CALIFORNIA

JOB NO. 142
SHEET NO. 3
SHEET 3 OF 4

#90068